


Achievement: Optimization of DCVG electrode position



- **Issue:** Neighboring coating defects on submerged pipeline can mask each other due to presence of reinforced concrete coating
- **Solution:** Elsyca studied different DCVG electrode positions and configurations in order to optimize DCVG survey
- **Results:**
 - Prove of masking of neighboring coating defects due to presence of reinforced concrete has been given
 - Optimal DCVG electrode spacing and position has been established